

FORM PTO-1449	U.S. DEPARTMENT OF COMMERCE PATENT AND TRADEMARK OFFICE			ATTY DKT NO. 1068-001	SERIAL NO. 10/651,054
INFORMATION DISCLOSURE STATEMENT BY APPLICANT			APPLICANT Thompson et al.		
			FILING DATE 8/28/2003	GROUP 3747	

## U.S. PATENT DOCUMENTS

EXAMINER INITIAL		DOCUMENT NO.	DATE	NAME	CL.	SUBCL.	FILING DATE IF APPROP.
---------------------	--	-----------------	------	------	-----	--------	---------------------------

## FOREIGN PATENT DOCUMENTS

		DOCUMENT NO.	DATE	COUNTRY	CL.	SUBCL.	TRANSLATION
--	--	-----------------	------	---------	-----	--------	-------------

YES

NO

## OTHER DOCUMENTS (Incl. Author, Title, Date, Pertinent pages, etc.)

TAM	A	Larry Carley, "Decoding On-Board Diagnostics," downloaded from <a href="http://www.aalcar.com">www.aalcar.com</a> , August 5, 2003, 4 pages
	B	"Lambda Sensor," downloaded from <a href="http://www.nernst.de/lambda-sensor.htm">www.nernst.de/lambda-sensor.htm</a> , August 12, 2003, 2 pages
	C	"Lambda Sensor (Titania) Waveform," downloaded from <a href="http://www.picotech.com/auto/waveforms/lambda_titania.html">www.picotech.com/auto/waveforms/lambda_titania.html</a> , August 12, 2003, 2 pages
	D	Product brochure for Lambda Sensor LSM 11, produced by Robert Bosch (Australia) Pty Ltd, dated October 17, 2001, 2 pages
	E	Peter J. Malone, "A Production Wide-Range AFR Sensor Response Diagnostic Algorithm for Direct-Injection Gasoline Application," SAE Technical Paper Series, 2001-01-0558, reprinted from Electronic Engine Controls 2001: Modeling, Controls, OBD and Neural Networks (SP-1585), presented at SAE 2001 World Congress, March 5-8, 2001, downloaded from <a href="http://www.delphi.com/pdf/techpapers/2001-01-0558.pdf">www.delphi.com/pdf/techpapers/2001-01-0558.pdf</a> , 8 pages
	F	Product brochure for Automotive Diagnostics Kit, downloaded from <a href="http://www.picotech.com/auto/automotive_kit.html">www.picotech.com/auto/automotive_kit.html</a> , August 14, 2003, 7 pages
	G	Product brochure for High Resolution Oscilloscopes for Automotive Diagnostics, downloaded from <a href="http://www.picotech.com/auto/automotive_oscilloscope.html">www.picotech.com/auto/automotive_oscilloscope.html</a> , August 14, 2003, 2 pages
	H	Media release, "Save Fuel and the Environment: Have Your Lambda (O <sub>2</sub> ) Sensor Checked Regularly in the Workshop," Robert Bosch (Australia) Pty Ltd, September 11, 2002, 1 page
	I	Mark Warren, "Tech to Tech: Standardizing On-Board Diagnostics," originally published in Autoln. Magazine, Vol. XLV, No. 6, June 1997, 3 pages
	J	Larry Hammer, "Platinum Spark Plugs: Justifying Their Cost," Tech Tip, Mighty Auto Parts, Mighty Distributing System of America, Inc., 4 pages
TAM	K	Colorado State University, "Case Study 8 - Ford P0304, P0301 Codes: 'Misfire - Problem or Solution?'" downloaded from <a href="http://www.obdiiicsu.com/Studies/2002CaseStudies/Misfire/Misfire.html">www.obdiiicsu.com/Studies/2002CaseStudies/Misfire/Misfire.html</a> , August 5, 2003, 3 pages

EXAMINER <i>John Mall</i>	DATE CONSIDERED 10/24/04
------------------------------	-----------------------------

EXAMINER: Initial if citation considered, whether or not citation is in conformance with MPEP 609; draw line through citation if not in conformance and not considered. Include copy of this form with next communication to applicant.